

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

404117307

Date Received:

03/05/2025

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10779

Name of Operator: SCOUT ENERGY MANAGEMENT LLC

Address: 13800 MONTFORT DRIVE SUITE 100

City: DALLAS State: TX Zip: 75240

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

Christian, Cody

Cody.Christian@scoutep.com

RangelyRegulatory@scoutep.com

Saint, John John.Saint@scoutep.com

Sanford, Anita Anita.Sanford@scoutep.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 718100270

Inspection Date: 02/24/2025

FIR Submit Date: 02/27/2025

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: SCOUT ENERGY MANAGEMENT LLC

Company Number: 10779

Address: 13800 MONTFORT DRIVE SUITE 100

City: DALLAS State: TX Zip: 75240

#### LOCATION - Location ID: 314456

Location Name: UNION PACIFIC-62N102W Number: 21SENW County: \_\_\_\_\_

Qtrqtr: SENW Sec: 21 Twp: 2N Range: 102W Meridian: 6

Latitude: 40.130561 Longitude: -108.850661

#### FACILITY - API Number: 05-103-00 Facility ID: 314456

Facility Name: UNION PACIFIC-62N102W Number: 21SENW

Qtrqtr: SENW Sec: 21 Twp: 2N Range: 102W Meridian: 6

Latitude: 40.130561 Longitude: -108.850661

### CORRECTIVE ACTIONS:

1 CA# 202745

Corrective Action: Comply with Rule 1002.f- Install or repair required stormwater and erosion control BMPs to manage runoff in a manner that minimizes erosion, degradation and sediment transport. Ensure BMPs are installed in accordance with good engineering practice, and maintained in a proper functioning condition. Ongoing stormwater monitoring/management required until site receives a passing final reclamation inspection.

Date: 03/06/2025

Response: CA COMPLETED

Date of Completion: 03/05/2025

Operator Comment: Installed stormwater and erosion control BMPs to manage runoff in a manner that minimizes erosion, degradation and sediment transport. See attached pictures.

ECMC Decision:

ECMC Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Anita Sanford

Signed:

Title: Sr. Regulatory Analyst

Date: 3/5/2025 3:36:04 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

404117318	pictures
-----------	----------

Total Attach: 1 Files