

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/03/2025

Submitted Date:

03/09/2025

Document Number:

711901997

**FIELD INSPECTION FORM**Loc ID 313685 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10657

Name of Operator: PCR OPERATING LLC

Address: 9211 BROADWAY ST #17493

City: SAN ANTONIO State: TX Zip: 78217

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

2 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		sperson@passcreekresource s.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224846	WELL	SI	08/03/2015	OW	087-05235	CLAR, L 1	SI

**General Comment:**

SHOWS NO INDICATION OF OPERATOR INVOLVEMENT- ELECTRICAL SERVICE PROVIDED BY XCEL ENERGY HAS BEEN DISCONNECTED TO ENTIRE ADENA FIELD- LANDOWNER/MINERAL OWNER EXPRESSED THAT LEASES HAVE EXPIRED- LOCATION SHOWS NO HOUSEKEEPING IN THE PAST (2-3) YEARS - FACILITY BUILDINGS ARE IN DISREPAIR- WINDOWS ALL BROKEN OUT, DOORS LEFT OPEN OR UNSECURED- FIELD OBSERVATIONS INDICATE THE ADENA FIELD HAS BEEN ABANDONED.

NOTE TO OPERATOR: CONTACT ECMC ENFORCEMENT GROUP & ENGINEERING GROUP FOR RESOLUTION DIRECTIVES. FOLLOW-UP FIR - CONDITIONS AT LOCATION REMAIN NON-COMPLIANT- SURFACE MAINTENANCE

Inspected Facilities

Facility ID: 224846

Type: WELL

API Number: 087-05235

Status: SI

Insp. Status: SI

Idle Well

Purpose: ☒ Shut In

☐ Temporarily Abandoned

Reminder:

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
SHOWS NO INDICATION OF OPERATOR INVOLVEMENT– ELECTRICAL SERVICE PROVIDED BY XCEL ENERGY HAS BEEN DISCONNECTED TO ENTIRE ADENA FIELD – LANDOWNER/MINERAL OWNER EXPRESSED THAT LEASES HAVE EXPIRED- LOCATION SHOWS NO HOUSEKEEPING IN THE PAST (2-3) YEARS – FACILITY BUILDINGS ARE IN DISREPAIR – WINDOWS ALL BROKEN OUT, DOORS LEFT OPEN OR UNSECURED – FIELD OBSERVATIONS INDICATE THE ADENA FIELD HAS BEEN ABANDONED. NOTE TO OPERATOR: CONTACT ECMC ENFORCEMENT GROUP & ENGINEERING GROUP FOR RESOLUTION DIRECTIVES. FOLLOW-UP FIR – CONDITIONS AT LOCATION REMAIN NON-COMPLIANT – SURFACE MAINTENANCE	schureky	03/09/2025