

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/06/2025

Submitted Date:

03/09/2025

Document Number:

711902007

FIELD INSPECTION FORM

Loc ID: 313674 Inspector Name: SCHURE, KYM On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10657
Name of Operator: PCR OPERATING LLC
Address: 9211 BROADWAY ST #17493
City: SAN ANTONIO State: TX Zip: 78217

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		sperson@passcreekresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224824	WELL	SI	11/11/1911	GW	087-05211	DEWEY 6	SI

General Comment:

SHOWS NO INDICATION OF OPERATOR INVOLVEMENT- ELECTRICAL SERVICE PROVIDED BY XCEL ENERGY HAS BEEN DISCONNECTED TO ENTIRE ADENA FIELD- LANDOWNER/MINERAL OWNER EXPRESSED THAT LEASES HAVE EXPIRED- LOCATION SHOWS NO HOUSEKEEPING IN THE PAST (2-3) YEARS - FACILITY BUILDINGS ARE IN DISREPAIR- WINDOWS ALL BROKEN OUT, DOORS LEFT OPEN OR UNSECURED- FIELD OBSERVATIONS INDICATE THE ADENA FIELD HAS BEEN ABANDONED.
NOTE TO OPERATOR: CONTACT ECMC ENFORCEMENT GROUP & ENGINEERING GROUP FOR RESOLUTION DIRECTIVES. FOLLOW-UP FIR - CONDITIONS AT LOCATION REMAIN NON-COMPLIANT- SURFACE MAINTENANCE

Inspected Facilities

Facility ID: 224824 Type: WELL API Number: 087-05211 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>SHOWS NO INDICATION OF OPERATOR INVOLVEMENT- ELECTRICAL SERVICE PROVIDED BY XCEL ENERGY HAS BEEN DISCONNECTED TO ENTIRE ADENA FIELD - LANDOWNER/MINERAL OWNER EXPRESSED THAT LEASES HAVE EXPIRED- LOCATION SHOWS NO HOUSEKEEPING IN THE PAST (2-3) YEARS - FACILITY BUILDINGS ARE IN DISREPAIR - WINDOWS ALL BROKEN OUT, DOORS LEFT OPEN OR UNSECURED - FIELD OBSERVATIONS INDICATE THE ADENA FIELD HAS BEEN ABANDONED.</p> <p>NOTE TO OPERATOR: CONTACT ECMC ENFORCEMENT GROUP & ENGINEERING GROUP FOR RESOLUTION DIRECTIVES. FOLLOW-UP FIR - CONDITIONS AT LOCATION REMAIN NON-COMPLIANT - SURFACE MAINTENANCE</p>	schureky	03/09/2025