

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/04/2025

Submitted Date:

03/04/2025

Document Number:

713301799**FIELD INSPECTION FORM**Loc ID 335610 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK	303-825-4822	cogcc@kpk.com	all inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240090	WELL	SI	05/01/2021	OW	123-07878	KIEFER GEORGE W UT B 1A	SI

General Comment:[well site inspection](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	electric/automation disconnect, metal panels		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	safety guards		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	pipd to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	electric/automation panels		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 240090 Type: WELL API Number: 123-07878 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well. Valves appeared to be closed at time of inspection

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 04/18/2024**BradenHead**Date of Last Brhd Test: 06/12/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
ECMC Inspection Report Summary Inspector Michael Kester, conducted an on-site Follow up inspection as per doc# 713300708, in accordance with Rule 901a, corrective actions appeared to have NOT been addressed Location: Kiefer George Unit B 1A Operator: KPK API#: 123-07878 County: Weld Mechanical integrity Testing, Rule 417b, corrective action date 4-18-2024 Weather conditions: clear and dry This inspection does not nullify any orders or NOAV from the ECMC	kesterm	03/04/2025

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404115775	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6944889
713301800	site pic	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6944887