

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/06/2025

Submitted Date:

03/10/2025

Document Number:

710100350

**FIELD INSPECTION FORM**Loc ID 332151 Inspector Name: Anderson, Laurel On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Noble, Legacy		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Legacy Noble Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
332151	LOCATION	AC			-	RITCHEY H-63N65W 27NWNW	EI
488298	TANK BATTERY	AC	10/23/2024		-	RITCHEY T3N-R65W-S27 L05	EI

**General Comment:**

ECMC Environmental Inspection of the following Chevron (Operator) facilities:

Ritchey 1-27 Tank Battery

Facility ID 488298

Location ID 332151

Any corrective actions from previous inspections, forms, or orders that have not been addressed are still applicable. There were no Operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Current site status:

-Minor weeds/trash/debris

-Unused equipment (loadout hose in grassy area northwest of ASTs)

-Inadequate secondary containment berms (burrows)

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type OTHER

Comment: Lack of maintenance/good housekeeping procedures. Minor weeds/trash/debris and unused equipment (loadout hose in grassy area northwest of ASTs) observed on location at the time of inspection (see photos).

Corrective Action: Comply with Rules 606 and 1002.f.(2).D.

Date: 03/17/2025

Overall Good: ☐**Spills:**

Type	Area	Volume

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

**Paint**Condition Other (Content) Other (Capacity) Other (Type) **Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient		Inadequate
Comment: Inadequate secondary containment. Animal burrows were observed in/around the horizontal separator and produced water vessel/crude oil AST earthen secondary containment berms (See Photos).				
Corrective Action: Comply with Rules 902.a., 902.b. and 902.c. Operators shall maintain earthen secondary containment berms to prevent pollution, adverse environmental impacts and the potential for unauthorized discharge of oil, condensate, gas, and/or other E&P Waste.				Date: 03/24/2025

**Venting:**Yes/No Comment: Corrective Action: Date: **Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities								
Facility ID:	332151	Type:	LOCATION	API Number: -	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12								
Facility ID:	488298	Type:	TANK	API Number: -	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12								

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404121778	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6952825">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6952825</a>
710100351	2025_0306_ Ritchey 1-27_Photo Documentation	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6952822">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6952822</a>