

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

404132582

Date Received:

03/18/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

Smelser, Wayne

wayne.smelser@state.co.us

ECMC INSPECTION SUMMARY:

FIR Document Number: 708303536

Inspection Date: 02/27/2025

FIR Submit Date: 03/06/2025

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335277

Location Name: GIBSON GULCH UNIT-66S91W Number: 30SWSW County: _____

Qtrqr: SWS Sec: 30 Twp: 6S Range: 91W Meridian: 6

Latitude: 39.492961 Longitude: -107.603731

FACILITY - API Number: 05-045-00 Facility ID: 335277

Facility Name: GIBSON GULCH UNIT-66S91W Number: 30SWSW

Qtrqr: SWS Sec: 30 Twp: 6S Range: 91W Meridian: 6

Latitude: 39.492961 Longitude: -107.603731

CORRECTIVE ACTIONS:

1 CA# 203044

Corrective Action: Install liner material to ensure spill or released materials will be maintained with containment structure.

Date: 04/06/2025

Response: CA COMPLETED

Date of Completion: 03/18/2025

The tank inside the secondary containment structure at this location is a fresh hot water supply storage tank.

Operator Comment: Secondary containment and liner requirements as found in ECMC Rule 603.o only apply to the storage of crude oil, condensate, and produced water; these requirements do not apply to the storage of fresh water. Fresh water from this tank may be heated during the winter time and used to un-thaw tanks or other equipment that may be frozen and need repair or replacement. Alternatively, fresh water is also kept in this tank specifically to provide a ready supply of fresh water to support any fire suppression needs in the local area. There is no produced water or condensate storage at this location, and there are no active flow lines located within the containment. The tank is clearly marked as "Fresh Water" (see attached pic). This corrective action has been addressed.

ECMC Decision: _____

ECMC Representative: _____

2 CA# 203045

Corrective Action: Remove stored supplies to comply with Rule 606.

Date: 01/14/2025

Response: CA COMPLETED

Date of Completion: 03/18/2025

Operator Comment: The hose noted inside the containment is necessary for use on this location, and is specifically needed/used to transfer water from the fresh water tank as needed; therefore, its is allowed per Rule 606.a. This corrective action has been addressed.

ECMC Decision: _____

ECMC Representative: _____

3 CA# 203046

Corrective Action: Remove weeds from location to comply with Rule 606.

Date: 01/14/2025

Response: CA COMPLETED

Date of Completion: 03/10/2025

Operator Comment: Weeds have been removed. Corrective action complete.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been completed / addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Environmental Lead

Date: 3/18/2025 4:40:10 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number Description

404132829	Tank is clearly marked for "Fresh Water"
-----------	--

Total Attach: 1 Files