

## Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC Juhan Booster Station

Location # 323868

Facility # 479766



Photo # 5034 From entrance to location




Photo # 5035 Location

## Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC Juhan Booster Station

Location # 323868

Facility # 479766



Photo # 5036 Location



Photo # 5037 Location

## Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC Juhan Booster Station

Location # 323868

Facility # 479766



Photo # 5038 Location



Photo # 5039 Location

## Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC Juhan Booster Station

Location # 323868

Facility # 479766



**Photo # 5040 Battery lacks required signage/not in compliance with CECMC rules**