

State of Colorado
Energy & Carbon Management Commission



Document Number:
404132783

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Date Received:
03/19/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:
2 of 2 CAs from the FIR responded to on this Form
2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name Phone Email
SIMCOE sjninspections@ikavenergy.co

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000809
Inspection Date: 05/30/2024 FIR Submit Date: 06/10/2024 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 333610

Location Name: BRIGGS GAS UNIT A-N33N8W Number: 35NWNW County:
Qtrqtr: NWN Sec: 35 Twp: 33N Range: 8W Meridian: N
Latitude: 37.064720 Longitude: -107.691632

FACILITY - API Number: 05-067-00 Facility ID: 333610

Facility Name: BRIGGS GAS UNIT A-N33N8W Number: 35NWNW
Qtrqtr: NWN Sec: 35 Twp: 33N Range: 8W Meridian: N
Latitude: 37.064720 Longitude: -107.691632

CORRECTIVE ACTIONS:

1 CA# 195773

Corrective Action: Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

Date: 07/10/2024

Response: CA COMPLETED

Date of Completion: 03/17/2025

Operator Comment: Bare areas reseeded.

ECMC Decision: _____

ECMC Representative: _____

2 CA# 195774

Corrective Action: Comply with rule 1002 Install or repair required BMPs.

Date: 06/17/2024

Response: CA COMPLETED

Date of Completion: 03/17/2025

Operator Comment: Rock added to gullies for erosion mitigation.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lisa Paulek

Signed: _____

Title: permitting specialist

Date: 3/19/2025 7:39:45 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404134779	Briggs A1 completion photos

Total Attach: 1 Files