

Inspection Photos  
Location Name: Joe Brophy 11-31 4N46W  
API Number: 125-10212



1. Lease sign at well location.



2. View of wellhead. Note stained soil around wellhead.

**Inspection Photos**  
**Location Name: Joe Brophy 11-31 4N46W**  
**API Number: 125-10212**



**3 Additional view of wellhead. Note stained soil around wellhead.**



**4. Well location overview.**

Inspection Photos

Location Name: Joe Brophy 11-31 4N46W

API Number: 125-10212




5. Lease sign at gathering location.



6. Gas meter inside meter shed.

**Inspection Photos**  
**Location Name: Joe Brophy 11-31 4N46W**  
**API Number: 125-10212**



**7. Calibration Log inside meter shed. Last recorded calibration date 3-3-23.**



**8. Gathering location overview.**