

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404139834

Date Received:

03/25/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

QB Energy

ecmc.inspections@qb-energy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708906094

Inspection Date: 03/24/2025

FIR Submit Date: 03/24/2025

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 334963

Location Name: COUEY-67S92W Number: 5SESW County: _____

Qtrqtr: SESW Sec: 5 Twp: 7S Range: 92W Meridian: 6

Latitude: 39.469820 Longitude: -107.691700

FACILITY - API Number: 05-045- -00 Facility ID: 334963

Facility Name: COUEY-67S92W Number: 5SESW

Qtrqtr: SESW Sec: 5 Twp: 7S Range: 92W Meridian: 6

Latitude: 39.469820 Longitude: -107.691700

CORRECTIVE ACTIONS:

1 CA# 203629

Corrective Action: All Production Facilities, valves, pipes, fittings, and vessels will be securely fastened or sealed, inspected at regular intervals, and maintained in good mechanical condition.

Date: 03/25/2025

Response: CA COMPLETED

Date of Completion: 03/25/2025

Operator Comment: Replaced tank valve bushing.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Justin Johnson

Signed:

Title: Compliance

Date: 3/25/2025 11:19:06 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404139834	FIR RESOLUTION SUBMITTED
404139840	Tank valve repaired.

Total Attach: 2 Files