

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/25/2025

Submitted Date:

03/25/2025

Document Number:

715501463

## FIELD INSPECTION FORM

 Loc ID 314714 Inspector Name: Burchett, Kirby On-Site Inspection  2A Doc Num: \_\_\_\_\_
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**ECMC Operator Number: 10779Name of Operator: SCOUT ENERGY MANAGEMENT LLCAddress: 13800 MONTFORT DRIVE SUITE 100City: DALLAS State: TX Zip: 75240**Contact Information:**

Contact Name	Phone	Email	Comment
Christian, Cody		Cody.Christian@scoutep.com	
Sanford, Anita	(970) 551-8313	Anita.Sanford@scoutep.com	
Saint, John		jsaint@scoutep.com	
Regulatory, Rangely		RangelyRegulatory@scoutep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229388	WELL	PR	02/01/2020	OW	103-07043	E RECTOR 8X	PR

**General Comment:**[ECMC Inspection Report Summary](#)

On Tuesday, 03/25/2025, Compliance Inspector Kirby Burchett, completed a field inspection and audit at Scout Energy Management LLC on the E Rector 8X well, Location #314714, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Colorado Parks and Wildlife (CPW) District with High Priority and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal operations no compliance issues were observed.

No follow up inspection is required.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	When no associated Tank battery is present at the Oil and Gas Location, the following information is required on the Well sign: Name of the Operator; Telephone number at which the Operator can be reached at all times; Telephone number for local emergency services (911 where available); The public road used to access the Well; Well name(s) and API number(s); The legal location of the Well(s) including the quarter/quarter section.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	As Location Entrance signs are replaced: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available) will be required.		
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:	<input type="text" value="(970) 675-3700"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment:	No		
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Expanded metal		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Submersible Pump	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank on containment		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		

Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 229388 Type: WELL API Number: 103-07043 Status: PR Insp. Status: PR

**Producing Well**

Comment: [January 2025 Production Report](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
				Material Handling And Spill Prevention		

Comment: [Operator is responsible for maintaining Best Management Practices \(BMPs\) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715501464	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6974453">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6974453</a>