

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404142228

Date Received:
03/26/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:
2 of 2 CAs from the FIR responded to on this Form
2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 95620
Name of Operator: WESTERN OPERATING COMPANY
Address: 1165 DELAWARE STREET #200
City: DENVER State: CO Zip: 80204
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>Heibel, Krystal</u>		<u>krystal.heibel@state.co.us</u>
		<u>steve@westernoperating.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 713900565
Inspection Date: 04/23/2024 FIR Submit Date: 04/25/2024 FIR Status:

Inspected Operator Information:

Company Name: WESTERN OPERATING COMPANY Company Number: 95620
Address: 1165 DELAWARE STREET #200
City: DENVER State: CO Zip: 80204

LOCATION - Location ID: 317009

Location Name: BOBCAT D SAND UNIT-61S56W Number: 9NWSW County:
Qtrqtr: NWS Sec: 9 Twp: 1S Range: 56W Meridian: 6
Latitude: 39.979870 Longitude: -103.664190

FACILITY - API Number: 05-121-00 Facility ID: 317009

Facility Name: BOBCAT D SAND UNIT-61S56W Number: 9NWSW
Qtrqtr: NWS Sec: 9 Twp: 1S Range: 56W Meridian: 6
Latitude: 39.979870 Longitude: -103.664190

CORRECTIVE ACTIONS:

1 CA# 194730

Corrective Action: In accordance with 913.d.(1) Operator will investigate impacts to soil, groundwater, and surface water as soon as the impacts are discovered. Additionally, Operator shall provide an explanation of how the volume of liquids spilled was calculated on the next Form 19 Supplemental Report and comply with Rule 912 series rules for Spills and Releases.

Date: 04/26/2024

Response: CA COMPLETED

Date of Completion: 04/29/2024

Operator Comment: Spill release # 486603. Due to the released fluids being non-E&P waste (gear lube oil) not regulated by ECMC, the volume released being less than CDPHE reportable volume, as well as compliance with Table 915-1 Western Operating Company respectfully requests to retract this ECMC Spill/Release report

ECMC Decision:

ECMC Representative:

2 CA# 194731

Corrective Action: Repair erosion and mainain BMP's per Rule 1002.f.

Date: 05/02/2024

Response: CA COMPLETED

Date of Completion: 03/14/2025

Operator Comment: Erosion along the access road has been remediated. See attached photos

ECMC Decision:

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lauren Glazier Signed:

Title: Consultant Date: 3/26/2025 2:19:48 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (http://ecmcweblink.state.co.us/) - Search by Document Number.

Table with 2 columns: Document Number, Description. Row 1: 404142247, Photos

Total Attach: 1 Files