

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/26/2025

Submitted Date:

03/26/2025

Document Number:

716300764**FIELD INSPECTION FORM**Loc ID 308368 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**ECMC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1875 LAWRENCE ST STE 1150City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
D DYKE, TRACY	719-846-7898	tracy.dyke@enrllc.com	<a href="#">Insp. w/ca's</a>
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269534	WELL	TA	03/11/2014	GW	071-07916	BEACON 11-18	TA

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	PHOTO 4: 1' RISER IS NOT MARKED.		
Corrective Action:	ALL UNUSED RISERS MUST BE CLEARLY MARKED OR REMOVED PER RULE 606. THIS IS THE SECOND NOTICE FOR THIS RISER IMMEDIATE ACTION IS REQUIRED.	Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	IS ACCESSABLE		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	269534	Type:	WELL	API Number:	071-07916	Status:	TA	Insp. Status:	TA
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned									
Reminder:									
Comment: LAST MIT 2/14/2024									
Corrective Action:									
Date:									
BradenHead									
Date of Last Brhd Test: 12/23/2011									
Annual Brhd Completed?									
Last Brhd Test Results									
Initial Surf Csg Pressure: 0									
Fluid Type:									
End Surf Csg Pressure: 0									
Comment: FORM 4 ON FILE									
Corrective Action:									
Date:									
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	274369	1230431	
	274369	403296269	
	274369	403296269	

**ECMC Comments**

Comment	User	Date
THIS IS A FOLLOW UP TO INSP. DOC #695110243, THE CA FOR TELEMTRY EQUIPMENT AND THE TWO 2" RISERS HAS BEEN ADDRESSED HOWEVER THE CA TO MARK THE 1" RISER HAS NOT BEEN ADDRESSED IMMEDIATE ACTION IS REQUIRED.	beardslt	03/26/2025

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716300765	INSP. PHOTOS	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6976004">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6976004</a>