

Weld OEM Spill Report Form

Submitted on	29 March 2025, 8:17AM
Receipt number	3457
Related form version	19

Company

Company name	KP KAUFFMAN
Address	1700 LINCOLN STREET SUITE 4550
City	DENVER
State	Colorado
Zip code	80203

Contact Information

Contact person	DAN MOTISI
Contact phone	303-909-0875
Contact email	dmotisi@kpk.com

About the Spill

Date incident occurred	03/28/2025
How long did the spill/ release occur	unknown
Was 9-1-1 called for this incident	Yes
Longitude	-104.850132
Latitude	40.107451
Fire depatment/district	Fort Lupton Fire
Where did the incident occur?	Oil and gas facility/pipeline

Oil and Gas Incident

Well site name	McHale #2
Section	26
Township	2N
Range	67W
Where did the spill occur	Pipeline
Have you submitted a form 19	Yes
Form 19 report number	404145889

Product Spilled

Product spilled	Crude Oil
Number of barrels spilled	1
Emergency precautions taken	N/A
Extremely hazardous substance	No
Acute or chronic health risks	No
Did the spill affect or end near a waterway, irrigation ditch, or a retention pond?	No
What caused the spill/release?	Equipment failure

Narrative

Include specific incident information and mitigation actions taken to stop and clean-up the spill/release

The landowner notified KPK and the Fort Lupton Fire Department of a spill associated with the Mchale #2 flowline. KPK immediately responded, shut in the well & blew down the flowline. KPK began excavating the impacted soil to expose the line and perform the necessary repairs. The impacted soil was stockpiled on plastic and temporarily stored on-site. An estimated 25-gallons (.79 bbls) was released and the volume of soil impacts are estimated to be approximately 10yd³. Figures and photos are attached. Further assessment is required to determine the extent of soil impacts. Assessment and remediation efforts are on-going.

Upload documentation collected	Mchale 2 Flowline Photos.pdf
Acknowledgement	I acknowledge that a written follow-up notice must be submitted to Weld County OEM/LEPC as soon as practicable after the release. The follow-up notice must update information included in the initial notice and provide information on actual response actions taken and advice regarding medical attention necessary for citizens exposed.