

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404146230

Date Received:
03/31/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10699
Name of Operator: OWN RESOURCES OPERATING LLC
Address: 305 S RIDGE STREET #6279
City: BRECKENRIDGE State: CO Zip: 80424

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Dolezal, Pat</u>	<u>970-332-3585</u>	<u>pat.dolezal@ownresources.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 698603031
Inspection Date: 01/14/2025 FIR Submit Date: 01/15/2025 FIR Status: _____

Inspected Operator Information:

Company Name: OWN RESOURCES OPERATING LLC Company Number: 10699
Address: 305 S RIDGE STREET #6279
City: BRECKENRIDGE State: CO Zip: 80424

LOCATION - Location ID: 304648

Location Name: BROPHY, JOE-64N47W Number: 14SWSE County: YUMA
Qtrqtr: SWSE Sec: 14 Twp: 4N Range: 47W Meridian: 6
Latitude: 40.309000 Longitude: -102.592490

FACILITY - API Number: 05-125-00 Facility ID: 269739

Facility Name: BROPHY, JOE Number: 10-14
Qtrqtr: SWSE Sec: 14 Twp: 4N Range: 47W Meridian: 6
Latitude: 40.309000 Longitude: -102.592490

CORRECTIVE ACTIONS:

1 CA# 201759

Corrective Action: Corrective action not performed or insufficient to prevent recurrence. Corrective action date remains the same to document period of non-compliance.

Control and contain spills/releases and clean up per Rule 912.a
Report spill or release of E&P waste or produced fluids Remove free fluids and contact COGCC EPS staff per Rule 912.b.

Date: 12/19/2024

Response: CA COMPLETED Date of Completion: 03/12/2025

Operator Comment: Replaced valve, spread gypsum, turned soil

ECMC Decision: _____

ECMC
Representative:

2 CA# 201760

Corrective Action: Corrective action not performed or insufficient to prevent recurrence. Corrective action date remains the same to document period of non-compliance.

Date: 12/04/2024

Inspect and service the wellhead, tree, and related surface control equipment to comply with Rule 603.c.(14).

Response: CA COMPLETED

Date of Completion: 03/12/2025

Operator
Comment: Replaced valve, spread gypsum, turned soil

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Pat Dolezal

Signed: _____

Title: Regulatory Specialist

Date: 3/31/2025 7:58:30 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

404146230	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files