

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404146413

Date Received:
03/31/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:
3 of 3 CAs from the FIR responded to on this Form
3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>. General</u>		<u>sjninspections@ikavenergy.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 714001980
Inspection Date: 03/18/2025 FIR Submit Date: 03/19/2025 FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC Company Number: 10749
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 326634

Location Name: THOMAS JACQUEZ GAS UNIT A-N33N10W Number: 14NESW County: _____
Qtrqr: NESW Sec: 14 Twp: 33N Range: 10W Meridian: N
Latitude: 37.101988 Longitude: -107.906999

FACILITY - API Number: 05-067-00 Facility ID: 326634

Facility Name: THOMAS JACQUEZ GAS UNIT A-N33N10W Number: 14NESW
Qtrqr: NESW Sec: 14 Twp: 33N Range: 10W Meridian: N
Latitude: 37.101988 Longitude: -107.906999

CORRECTIVE ACTIONS:

1 CA# 203445

Corrective Action: Comply with rule 605. Install or repair labels. Date: 04/19/2025

Response: CA COMPLETED Date of Completion: 03/28/2025

Operator Comment: Labels replaced.

ECMC Decision: _____

ECMC Representative: _____

2 CA# 203446

Corrective Action: Conduct revegetation within portions of the interim reclamation area with bare soils and sparse vegetative cover by 5/15/2025.

Date: 05/15/2025

Response: CA COMPLETED

Date of Completion: 03/28/2025

Operator Comment: Cut slopes reseeded.

ECMC Decision: _____

ECMC Representative: _____

3 CA# 203447

Corrective Action: a. Comply with rule 1002 Install or repair required BMPs.
b. Erosion controls need to be installed and maintained on location cutslope until bare soils are stabilized with desirable perennial vegetation

Date: 04/02/2025

Response: CA COMPLETED

Date of Completion: 03/28/2025

Operator Comment: Erosion mitigation installed.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions completed. See attachment for photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lisa Paulek

Signed: _____

Title: permitting specialist

Date: 3/31/2025 9:55:46 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
404146413	FIR RESOLUTION SUBMITTED
404146414	Thomas Jacquez A2 completion photos

Total Attach: 2 Files