

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/07/2025

Submitted Date:

04/08/2025

Document Number:

713602036

**FIELD INSPECTION FORM**

Loc ID 307327 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10705  
Name of Operator: EVERGREEN NATURAL RESOURCES LLC  
Address: 1875 LAWRENCE ST STE 1150  
City: DENVER State: CO Zip: 80202

**Findings:**

2 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, Evergreen		cogcc.evergreen@enrllc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217460	WELL	SI	04/01/2024	CBM	071-06237	GROSSO 23-21	RI

**General Comment:**

This is a follow up inspection at the GROSSO #23-21 wellsite.  
See attached photos and additional details within this report.

**Location**

**Lease Road:**

Type Access

comment:

Corrective ActionL

Date:

Overall Good:

**Signs/Marker:**

Type WELLHEAD

Comment:

Corrective Action:

Date:

**Emergency Contact Number:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

Comment:

Corrective Action:

Date:

Overall Good:

**Spills:**

Type Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: The erosion previously observed along the northwest cut slope and at the drainage crossing have been repaired and reseeded. The culverts along the road have been cleaned out and are maintained.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713602037	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6994657">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6994657</a>