

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/08/2025

Submitted Date:

04/08/2025

Document Number:

699507074

**FIELD INSPECTION FORM**Loc ID 463062 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10243

Name of Operator: GMT EXPLORATION COMPANY LLC

Address: 4949 S NIAGARA ST SUITE 250

City: DENVER State: CO Zip: 80237

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Eberhardt, Whitney	303-586-9289	w.eberhardt@gmtexploration.com	Principal Agent

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
463061	WELL	EP	03/05/2021	LO	001-10415	L&S 3-65-12-11-10HN	ND

**General Comment:**

EP inspection

Location					
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment:					Date: _____
Corrective Action:					
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities

Facility ID: 463061

Type: WELL

API Number: 001-10415

Status: EP

Insp. Status: ND

Idle Well

Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder:

Comment: ND

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
At time of inspection no wells have been drilled on location. 10H well that has expired permit needs to be changed to Abandoned Location status.	medinaj	04/08/2025
This inspection does not nullify any orders or corrective actions from the ECMC At time of inspection weather conditions were warm, overcast, calm.		

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699507075	inspection pictures	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6995429">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6995429</a>