

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/07/2025

Submitted Date:

04/09/2025

Document Number:

700300793**FIELD INSPECTION FORM**Loc ID 326115 Inspector Name: LABOWSKIE, STEVE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10663Name of Operator: ENDURING RESOURCES LLCAddress: 6300 S SYRACUSE WAY, SUITE 525City: CENTENNIAL State: CO Zip: 80111**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Walter, Kyle		kwalter@enduringresources.com	All SW Inspections
Huntington, Heather		hhuntington@enduringresources.com	All SW Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215889	WELL	AC	09/19/1998	OBW	067-07494	DAY-V-RANCH 35-2	AC

General Comment:

Inspection to witness MIT to verify well integrity and maintain use as observation/monitor well. 670 on tubing and 350 psi on casing on arrival. Well not pre-tested or stabilized in advance. Operator chose to blow down both tubing and casing in order to have a lower pressure test and still maintain + 300 psi differential. Test was run additional 10 minutes to fully stabilize.

Well report as SI on monthly Form 7. SI defined as readily able to produce to sales. No production equipment or sales line on location.

No 24-hour operator contact number or emergency services number on well sign. See signs and markers section for CA.

Mature dead noxious weeds from last growth cycle observed near center of location.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: No 24-hour operator contact number or emergency service number on well sign

Corrective Action: Install functioning contact numbers per Rule 605 Date: 05/09/2025

Good Housekeeping:

Type	WEEDS		
Comment:	Mature scotch thistles from last seasons growth cycle with seed observed near wellhead/center of location. These need to be controlled/managed. Removal can reduce regenration/spread of listed noxious weed species.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:	acesible, annual BH test submitted		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 215889

Type: WELL

API Number: 067-07494

Status: AC

Insp. Status: AC

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder:

Comment: Well used to monitor quarterly formation pressure

Upon arrival, tubing had 623 psig and casing 350 psig. Operator blew both down prior to test.

With pump truck casing was pressured up to 539 psig, 5 min 539, 10 min 536, 15 min 528, 20 min 526, 25 min 525. Test run additional 10 min to obtain full stabilization. No bradehead pressures observed.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700300800	INSPECTION PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6997691