

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404109278

Date Received:
04/10/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
TEP		COGCCInspectionReports@terraep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708302921
Inspection Date: 10/15/2024 FIR Submit Date: 10/16/2024 FIR Status:

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 334724

Location Name: HOOAGLUND-67S95W Number: 2NWNW County:
Qtrqtr: NWN Sec: 2 Twp: 7S Range: 95W Meridian: 6
W
Latitude: 39.471019 Longitude: -107.973441

FACILITY - API Number: 05-045-00 Facility ID: 334724

Facility Name: HOOAGLUND-67S95W Number: 2NWNW
Qtrqtr: NWN Sec: 2 Twp: 7S Range: 95W Meridian: 6
W
Latitude: 39.471019 Longitude: -107.973441

CORRECTIVE ACTIONS:

1 CA# 199812

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 11/01/2024

Response: CA COMPLETED Date of Completion: 12/05/2024

Rill has been repaired and the access road has been bladed/graded to increase stabilization. Corrective Action complete.

Operator: _____
Comment: _____

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Rill has been repaired and the access road has been bladed/graded to increase stabilization. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith Signed: _____

Title: TEP Representative Date: 4/10/2025 5:55:33 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404109278	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files