

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/26/2025

Submitted Date:

04/02/2025

Document Number:

717100131

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
Rollins, Grace _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	All Inspections
Robinson, Taylor		taylor.robinson@state.co.us	
Mickelson, Erik		Erik_Mickelson@oxy.com	Oxy Environmental
Graber, Nikki		nikki.graber@state.co.us	
Kiel, Macy	970-515-1110	Macy_Kiel@oxy.com	Staff Environmental Engineer

General Comment:

ECMC Environmental Field Inspection Report Summary
Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill ID: 486756
Spill Name: Iceman State 32N-A16HZ
Facility ID: 481351
Reported Date of Discovery: 04/23/2024
Date of Inspection: 03/26/2025

Current site status:
-Excavation has been backfilled.
-No environmental impacts were visible.
-Separator has been removed from the Spill area.
-The most recent Form 19 (Doc. # 403947642) was submitted on 10/07/2024; the Operator's request for closure of Spill ID 486756 was removed at the time of form approval by ECMC on 11/15/2024.

See attached corrective actions. A Supplemental Form 19 is required.

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Spill ID 486756 was created to address the remediation of impacts identified at the Iceman State 32N-A16HZ facility. The excavation has been backfilled. No environmental impacts were visible. The most recent Form 19 (Doc. # Doc. # 403947642) was submitted on 10/07/2024; the Operator's request for closure of Spill ID 486756 was removed at the time of approval by ECMC on 11/15/2024.

Corrective Action: In accordance with Rule 912.b.(6), Operator shall provide an updated Form 19 – Supplemental requesting closure of Spill ID 486756. If the remediation required by the COA on Form 19 Doc. # 403947642 has not been completed, Operator shall also provide a Form 27 – Initial for the ongoing remediation.

Date: 04/18/2025

Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404153316	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6990565
717100132	ECMC Photo Log_Iceman State 32N-A16HZ	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6990560