

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/11/2025

Submitted Date:

04/11/2025

Document Number:

713301968

**FIELD INSPECTION FORM**

Loc ID 488534 Inspector Name: Kester, Michael On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, KerrMcGee	970-515-1500	ECMCInspections@Oxy.com	<a href="#">all inspections</a>
Silver, Randy	720-827-6688	randy.silver@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
489090	WELL	DG	02/21/2025		123-52905	TULIP WEST 30-2HZ	DG

**General Comment:**

[drilling site inspection](#)

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	DRILLING/RECOMP		
Comment:	good		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	wind wall, half way		
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 489090 Type: WELL API Number: 123-52905 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: Precision 562 Pusher/Rig Manager: chuck  
 Permit Posted: SATISFACTORY Access Sign: SATISFACTORY

**Well Control Equipment:**

Pipe Ram: YES Blind Ram: YES Hydril Type: YES  
 Pressure Test BOP: Pass Test Pressure PSI: 5000 Safety Plan: YES

**Drill Fluids**

**Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: YES Semi-Closed Loop: NO  
 Multi-Well: YES Disposal Location: waste connection

**Comment:** replaced top drive unit after brake fire, testing complete, start drilling

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<a href="#">Audit of scout card and related documents</a> <a href="#">Routine Drilling site inspection</a>	kesterm	04/11/2025
<a href="#">This inspection does not nullify any orders or NOAV from the ECMC</a>		

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713301969	site pic	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7002097">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7002097</a>