

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404164559

Date Received:
04/15/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 5 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>TEP</u>		<u>COGCCInspectionReports@terraep.com</u>
<u>Heil, John</u>		<u>john.heil@state.co.us</u>
<u>Toews, Wesley</u>		<u>wtoews@blm.gov</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 708906125
Inspection Date: 03/25/2025 FIR Submit Date: 03/28/2025 FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: _____

Location Name: _____ Number: _____ County: _____
Qtrqtr: NENW Sec: 17 Twp: 7S Range: 91W Meridian: 6
Latitude: 39.452721 Longitude: -107.581499

FACILITY - API Number: 05-045-00 Facility ID: 454256

Facility Name: CASTLE SPRINGS COMPRESSOR STATION Number: _____
Qtrqtr: NENW Sec: 17 Twp: 7S Range: 91W Meridian: 6
Latitude: 39.452721 Longitude: -107.581499

CORRECTIVE ACTIONS:

1 CA# 203750

Corrective Action: Comply with CECMC wildlife rules Date: 04/04/2025

Response: CA COMPLETED Date of Completion: 04/11/2025

Operator: _____
Comment: ECMC Rule 1202.a.(4) requires installation of fencing, netting or other exclusion devices at "... new drilling pits, production pits, and other pits associated with oil and gas operations that are intended to contain fluids." The chemical tank / containment trough does not meet the definition of a "pit" per ECMC rules, and therefore ...

fencing, netting, and other exclusion devices are not required for these ancillary chemical tanks that are placed within a secondary containment trough. It has been TEP's experience that placing a net or wire mesh covering over such tanks has a detrimental affect upon wildlife. Birds and even small rodents are attracted to the rain water / snow melt that accumulates inside the trough. Once the birds / rodents get inside the containment, they often times cannot find their way back out and become trapped and succumb inside the trough. To prevent birds and rodents from becoming trapped inside the netted structures, TEP is removing any existing nets and mesh coverings from the chemical containment troughs. TEP will install escape ramps / boards to prevent any entrapment inside the trough. In addition, TEP is actively inspecting the containment structures to ensure that the chemical tanks are not leaking, and also to remove any fresh water that may be accumulating inside the containment. This corrective action has been addressed.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: ECMC Rule 1202.a.(4) requires installation of fencing, netting or other exclusion devices at "... new drilling pits, production pits, and other pits associated with oil and gas operations that are intended to contain fluids." The chemical tank / containment trough does not meet the definition of a "pit" per ECMC rules, and therefore ... fencing, netting, and other exclusion devices are not required for these ancillary chemical tanks that are placed within a secondary containment trough. It has been TEP's experience that placing a net or wire mesh covering over such tanks has a detrimental affect upon wildlife. Birds and even small rodents are attracted to the rain water / snow melt that accumulates inside the trough. Once the birds / rodents get inside the containment, they often times cannot find their way back out and become trapped and succumb inside the trough. To prevent birds and rodents from becoming trapped inside the netted structures, TEP is removing any existing nets and mesh coverings from the chemical containment troughs. TEP will install escape ramps / boards to prevent any entrapment inside the trough. In addition, TEP is actively inspecting the containment structures to ensure that the chemical tanks are not leaking, and also to remove any fresh water that may be accumulating inside the containment. This corrective action has been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Environmental Lead

Date: 4/15/2025 10:46:42 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404164559	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files