

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Hi Melissa,

Thanks for the chance to take a look. I think the BMPs you have provided look good for this location. Coupled with the fact that winter range conditions are looking fairly mild right now, CPW does not have any concerns or additional requests. Please let us know if you have any questions, or we can help with additional information.

Take care,

On Mon, Apr 14, 2025 at 12:15 PM Melissa Luke <mluke@terraep.com> wrote:

Good afternoon, Taylor –

We are planning on doing a casing repair on the WILLIAMS #RWF 41-33.

Under ECMC Rule 312, operators are required to consult with CPW when non-routine maintenance operations are planned, which includes well repairs and plugging operation.

We have included the identified HPHs associated with the location and are planning to begin operations upon approval by ECMC.

As a part of this process, we are required to attach any agreed upon BMPs and correspondence between CPW and the operator documenting consultation. To ensure proper well operations, TEP has proposed the Best Management Practices listed below for implementation during planned activities to minimize potential impacts to wildlife. If additional BMPs are necessary, please let me know. THANK YOU!!

Pad Name	Well Name	API	Surface Ownership	Mineral Ownership	Planned Operation	Rule 1202.d Habitats	Rule 1202.c.(1) Habitats	Rule 309.e Habitats	Federal Critical Habitats
Williams RWF 342-33	WILLIAMS #RWF 41-33	05-045-15444	FEE	FEDERAL	CASING WORKOVER	ELK SEVERE WINTER RANGE ELK WINTER CONCENTRATION AREA MULE DEER SEVERE WINTER RANGE MULE DEER WINTER CONCENTRATION AREA	NONE	NONE	NONE

Associated BMP's

Mule Deer and Elk BMPs

1. Wildlife – Minimization: To minimize the potential for wildlife related traffic accidents, TEP has implemented speed restrictions for all lease roads and requires that all TEP employees and contractors adhere to these posted speed restrictions.
2. Wildlife – Minimization: TEP will make best efforts to minimize operations at these location during winter months by conducting operations, when possible, between 9:00am to 4:00pm when wildlife activity minimal.
3. Wildlife – Minimization: TEP will minimize vehicle numbers and traffic by carpooling to the site whenever possible.

Melissa Luke

Regulatory Specialist

TEP Rocky Mountain LLC

(Terra Energy Partners LLC)

PO Box 370 | 1058 CR 215 | Parachute, CO 81635

Office Phone (970) 263-2721

Cell Phone (970) 200-7201

Email- mluke@terraep.com



This message and any related attachments are intended only for the use of the addressee(s) and may contain information that is PRIVILEGED and CONFIDENTIAL. If you are not the intended recipient(s), you are hereby notified that any dissemination of this communication is strictly prohibited. If you have received this communication in error, please erase all copies of the message and its attachments and notify the sender immediately.