

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/08/2025

Submitted Date:

04/09/2025

Document Number:

710500477

FIELD INSPECTION FORMLoc ID _____ Inspector Name: _____ On-Site Inspection ☐
Sanchez, Chris 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, ENR	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections
Serna, Abe		abe.serna@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266576	WELL	PR	12/01/2024	GW	071-07828	KLINGON 31-32 TR	EI
270538	PIT	AC			-	KLINGON 31-32 ONSITE	EI

General Comment:[This is an Environmental Inspection for the Klingon 31-32 TR well location located in Las Animas County, Colorado.](#)

Location**Lease Road:**

Type	Access		
comment:	At the time of inspection, signs of erosion were present in and along the access road.		
Corrective Action:	Install or repair required BMPs per Rule 1002.f.(2)C	Date:	04/18/2025

Overall Good: ☐**Signs/Marker:**

Type			
Comment:	Placard located on meter house		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:			
		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
Produced Water	WELLHEAD			
Comment:	At the time of inspection, evidence of a historical leak was identified at the wellhead. Impacted soils were observed from the wellhead traveling south along the eastern edge of the well pad, see attached photos.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date: 04/10/2025

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	266576	Type:	WELL	API Number:	071-07828	Status:	PR	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	270538	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 270538Lat: 37.133963Long: -104.801667Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: Corrective Action: Date:

Monitoring:

Monitoring Type

Comment

Chain

ECMC Comments

Comment	User	Date
If historical impacts at the wellhead are determined to be a reportable release, Operator shall provide notifications in accordance with Rule 912.b.	sanchezcc	04/09/2025

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404158538	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6996340
710500478	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6996333