

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/08/2025

Submitted Date:

04/09/2025

Document Number:

714002062**FIELD INSPECTION FORM**Loc ID 311911 Inspector Name: Mcdonough, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10840Name of Operator: ABUNDANCE ENERGY SERVICES LLCAddress: 2121 S COLUMBIA AVE SUITE 101City: TULSA State: OK Zip: 74114**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		sjbcompliance@abundance-energy.com	
		aprice@abundance-energy.com	principal agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216506	WELL	PR	02/03/2004	GW	067-08112	HAHN 1-A	RI
276603	WELL	PR	06/08/2006	GW	067-09022	IGE 100	RI
290038	WELL	PR	01/24/2018	CBM	067-09346	IGE 135	RI

General Comment:

On 4/8/2025 Reclamation Specialist Corey McDonough conducted an Interim Reclamation and Stormwater Inspection at Abundance Energy Services Hahn, Ige Location in La Plata County, Colorado. This is a follow up inspection to inspection doc # 714000652. Any Corrective Actions from previous inspections that have not been addressed are still applicable.

This inspection is also in response to resolution doc # 403773384 stating corrective actions' have been completed. It was observed in this inspection that the previously observed corrective actions' regarding weedy debris and stormwater have been resolved.

During the inspection the following compliance issues were observed:

- Produced water labels (operator)

Refer to the "Signs/Markers" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Location				
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:	Produced water tanks not displaying current operator.			
Corrective Action:	Update signs per rule 605a.			Date: 05/09/2025
Emergency Contact Number:				
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:	<input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date: <input type="text"/>
Flaring:				
Type				
Comment:				
Corrective Action:				Date: <input type="text"/>

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment [No waste/weedy debris observed on location.](#)

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment [No unused equipment observed on location.](#)

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? PassProduction areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment Vegetation is progressing within the interim reclamation areas to 1003 standards and no Colorado state listed noxious weeds were observed – Vegetation is mostly perennial grass/desirable species. Continue to monitor and manage location to comply with 1003 vegetation requirements.

Corrective Action _____ Date _____

Overall Interim Reclamation In Process**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [At the time of the inspection, no storm water erosion issues were observed. Continue monitoring and managing storm water and erosion controls to ensure compliance with storm water regulations.](#)

Corrective Action: _____

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404159179	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6996885
714002072	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6996875