

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/04/2025

Submitted Date:

04/11/2025

Document Number:

693808308

FIELD INSPECTION FORM

Loc ID 316829 Inspector Name: BROWNING, CHUCK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10841
Name of Operator: AMERICAN HELIUM LLC
Address: 23501 CINCO RANCH BLVD, B244
City: KATY State: TX Zip: 77494

Findings:

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Joyner, Ryan	970.385.6289	rjoyner@blm.gov	Tres Rios
Lapham, Ken	979-877-4951	klapham@americanhelium.us	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263695	WELL	SI	03/01/2023	GW	113-06103	ANDY'S MESA FEDERAL 28	TA

General Comment:

COGCC staff performed a follow up field inspection on 4/4/2025. Followup to inspection doc#693807827 on 10/10/2024. Issues were found requiring corrective action. See inspection text and photos for details. Any Corrective Actions from previous inspections that have not been addressed are still applicable. ECMC staff witnessed Bradenhead test to comply with CA.

Location

Lease Road:			
	Type Access		
comment:			
Corrective ActionL			Date:
	Type Main		
comment:			
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
	Type TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible.		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 11/15/2024
	Type WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
	Comment: 435-631-2239		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
	Type WELLHEAD		
Comment:	Panel fence		
Corrective Action:			Date:

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:	Meter runs disconnected from separators and blind flanged on each end.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		38.054373,-108.647627
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	<100 BBLs	STEEL AST		38.054373,-108.647627
Comment:	<p>All open-topped Tanks will be equipped with screens or other appropriate equipment to prevent entry by wildlife, including birds and bats. Tanks is vented through mess covered opening, signage on tank indicates produced water and condensate. Operator stated that vessels are operational blowdown tanks. Per Rule 608.a(9), crude oil and condensate storage tanks will function as sealed and ventless</p>				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 263695 Type: WELL API Number: 113-06103 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well shut in and locked out by BLM.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/04/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: GAS

End Surf Csg Pressure: 0

Comment: Perform Bradenhead test. 0 psi on gauge. Slight vaccum. No fluid. No pressure or flow after 30 min.

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404162252	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7001475
693808309	Inspection photos 4/4/2025	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7001466