

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/KP 34-18

Location ID: 335529

Date: 4/16/2025



Location Overview – Photo #08203



Location – Photo #08204

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/KP 34-18

Location ID: 335529

Date: 4/16/2025



Location – Photo #08224



Location – Photo #08225

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/KP 34-18

Location ID: 335529

Date: 4/16/2025



Location – Photo #08209



Location – Photo #08208

Audit Photos


Location Name: TEP ROCKY MOUNTAIN LLC, Federal/KP 34-18

Location ID: 335529

Date: 4/16/2025



Location – Photo #08226



Illegible Wellhead Sign – Photo #08205

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/KP 34-18

Location ID: 335529

Date: 4/16/2025



Illegible Wellhead Sign – Photo #08206



Illegible Wellhead Sign – Photo #08207

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/KP 34-18

Location ID: 335529

Date: 4/16/2025



Staining in Tank Containment – Photo #08223