

**COLORADO OIL & GAS CONSERVATION COMMISSION**  
**FIELD INSPECTION REPORT**



<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION	1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100
API No. 05- <u>001 - 08328</u>	LEASE NAME: <u>Bass Box Elder 6-32</u>
LOCATION: <u>SWSE 6-35-65W</u>	OPERATOR: <u>Thorofare Res</u>
DATE: <u>4/1/98</u>	INSPECTOR: <u>LAR</u>
Insp. Type: <u>CA</u> Insp. Status: <u>PA</u> PA: Y    N	Pass/Fail: P    F    Viol.: Y    N    NOV: Y    N

INSPECTION ITEM	COMMENTS	INPUT
<b>Well ID Signs</b> (Rule 210, 604.c(4))		
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904, 905)		
<b>Fences</b> (Rule 603.b.7, 604.C.(3), 1002.A)		
<b>Tank Battery Equipment</b> (Rule 603.b.3, 604)		
<b>Fire Walls/Berms/Dikes</b> (Rule 603.b.12, 604)		
<b>General Housekeeping</b> (Rule 603)		
<b>Spills (Oil/Water)</b> (Rule 907)		
<b>Bradenhead</b> (Rule 207.b)		
<b>Drilling Well/Workover</b> (Rule 317)		
<b>Surface Rehabilitation</b> (Rule 1002, 1003, 1004, 1103)		
<b>Miscellaneous</b>	<u>Arrived on location @ 15:15 witnessed running of cement bond log. cement top at 935' RTH w/wireline &amp; perf'd at 598' SDFN Left location @ 17:00</u>	

**CORRECTIVE ACTION REQUIRED:**

Date Corrective Action Required By: \_\_\_\_\_ Date Remedied: \_\_\_\_\_

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.