

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404177711

Date Received:

04/24/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714001954

Inspection Date: 03/12/2025

FIR Submit Date: 03/14/2025

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 333970

Location Name: BLACK GAS UNIT 21-22-M34N8W Number: 22SENE County: _____

Qtrqr: SENE Sec: 22 Twp: 34N Range: 8W Meridian: M

Latitude: 37.179521 Longitude: -107.699574

FACILITY - API Number: 05-067-00 Facility ID: 333970

Facility Name: BLACK GAS UNIT 21-22-M34N8W Number: 22SENE

Qtrqr: SENE Sec: 22 Twp: 34N Range: 8W Meridian: M

Latitude: 37.179521 Longitude: -107.699574

CORRECTIVE ACTIONS:

1 CA# 203343

Corrective Action: Comply with rule 605. Install or repair labels.

Date: 04/14/2025

Response: CA COMPLETED

Date of Completion: 04/22/2025

Operator
Comment:

Labels replaced.

ECMC Decision: _____

ECMC
Representative:

2 CA# 203344

Corrective Action: Maintain equipment and clean up impacted material and dispose per Rule 1002.

Date: 03/21/2025

Response: CA COMPLETED

Date of Completion: 04/22/2025

Operator
Comment: Impacted material removed

ECMC Decision:

ECMC
Representative:

3 CA# 203345

Corrective Action: Conduct revegetation within portions of the interim reclamation area with bare soils and sparse vegetative cover by 5/15/2025.

Date: 05/15/2025

Response: CA COMPLETED

Date of Completion: 04/23/2025

Operator
Comment: Bare areas reseeded.

ECMC Decision:

ECMC
Representative:

4 CA# 203346

Corrective Action: Stormwater controls (ie: BMPs) and erosion controls are needed on revegetating soils until the location is stabilized with desirable perennial vegetation.

Date: 03/21/2025

Response: CA COMPLETED

Date of Completion: 04/23/2025

Operator
Comment: Bare areas reseeded.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions completed. See attachment for photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lisa Paulek

Signed:

Title: permitting specialist

Date: 4/24/2025 1:14:33 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404177718	Black 21-22 2 Completion photos

Total Attach: 1 Files