

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404181446

Date Received:

04/28/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Luke Kelly

970-939-6353

lkelly@civiresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 718700266

Inspection Date: 04/01/2025

FIR Submit Date: 04/03/2025

FIR Status: _____

Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Company Number: 8960

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 428278

Location Name: Antelope Number: M-31 County: _____

Qtrqtr: SENW Sec: 31 Twp: 5N Range: 62W Meridian: 6

Latitude: 40.356720 Longitude: -104.366220

FACILITY - API Number: 05-123-00 Facility ID: 428278

Facility Name: Antelope Number: M-31

Qtrqtr: SENW Sec: 31 Twp: 5N Range: 62W Meridian: 6

Latitude: 40.356720 Longitude: -104.366220

CORRECTIVE ACTIONS:

1 CA# 203871

Corrective Action: Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

Date: _____

Response: CA COMPLETED

Date of Completion: 04/28/2025

Operator has addressed the vegetation issue in order to comply with Rule 1004. This location has been inter-seeded. Additional crimped straw mulch was decided against in order to minimize disturbance to new seedlings

Operator Comment:	and existing perennial grasses that were observed
ECMC Decision:	
ECMC Representative:	

<u>OPERATOR COMMENT AND SUBMITTAL</u>	
Comment:	CA follow-up has been completed for this location.
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: Aubrey Noonan	Signed:
Title: Sr Regulatory Analyst	Date: 4/28/2025 1:16:58 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404181446	FIR RESOLUTION SUBMITTED
404181468	Inspection Resolution

Total Attach: 2 Files