



99999999

*Travel 2.0
inspect 6.5* *ok 9-25-97*

OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT

FACTORY INSPECTION

1120 Lincoln Street, Suite 801
Denver, CO 80203
(303)894-2100☒ NOTICE OF SATISFACTORY INSPECTION

API No. 05- <u>103 - 9607</u>	LEASE NAME: <u>EXxon #1</u>				
LOCATION: <u>Sec 18, T3S, R95W</u>	OPERATOR: <u>Strachan Expl</u>				
DATE: <u>9-12-97</u>	INSPECTOR: <u>Massey</u>				
Insp. Type: <u>CA</u>	Insp. Status: <u>PA</u>	PA: Y <u>(N)</u>	Pass/Fail: <u>P</u> F	Viol.: Y <u>(N)</u>	NOV: Y <u>(N)</u>

INSPECTION ITEM

COMMENTS

INPUT

Well ID Signs (Rule 210, 604.c(4))	<u>ok</u>	
Pits (Reserve/Production) (Rule 902, 903, 904, 905)	<u>n/a</u>	
Fences (Rule 603.b.7, 604.C.(3), 1002.A)	<u>(C)</u>	
Tank Battery Equipment (Rule 603.b.3, 604)		
Fire Walls/Berms/Dikes (Rule 603.b.12, 604)		
General Housekeeping (Rule 603)		
Spills (Oil/Water) (Rule 907)		
Bradenhead (Rule 207.b)		
Drilling Well/Workover (Rule 317)		<u>Witnessed P+A Set 75 sks 2485'-2170'</u> <u>Set 35 sks 165'-surf.</u>
Surface Rehabilitation (Rule 1002, 1003, 1004, 1103)		
Miscellaneous		



00375227

CORRECTIVE ACTION REQUIRED: none

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.