

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404195122

Date Received:
05/08/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:
2 of 2 CAs from the FIR responded to on this Form
2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10840
Name of Operator: ABUNDANCE ENERGY SERVICES LLC
Address: 2121 S COLUMBIA AVE SUITE 101
City: TULSA State: OK Zip: 74114
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
		sjbcompliance@abundance-energy.com
		aprice@abundance-energy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714002063
Inspection Date: 04/08/2025 FIR Submit Date: 04/09/2025 FIR Status:

Inspected Operator Information:

Company Name: ABUNDANCE ENERGY SERVICES LLC Company Number: 10840
Address: 2121 S COLUMBIA AVE SUITE 101
City: TULSA State: OK Zip: 74114

LOCATION - Location ID: 325156

Location Name: FORD-OLSON UNIT-N33N8W Number: 9SESE County:
Qtrqtr: SESE Sec: 9 Twp: 33N Range: 8W Meridian: N
Latitude: 37.115040 Longitude: -107.718350

FACILITY - API Number: 05-067- -00 Facility ID: 325156

Facility Name: FORD-OLSON UNIT-N33N8W Number: 9SESE
Qtrqtr: SESE Sec: 9 Twp: 33N Range: 8W Meridian: N
Latitude: 37.115040 Longitude: -107.718350

CORRECTIVE ACTIONS:

1 CA# 203950

Corrective Action: Conduct revegetation/reseeding efforts within portions of the interim reclamation area with bare soils and sparse vegetation. Date:

Response: CA COMPLETED Date of Completion: 05/01/2025

Operator Comment: Areas of the interim reclamation with bare and sparse vegetation have had top soil and amendment added, re-seeded and mulched. These areas will be monitored until desirable vegetation is achieved.

ECMC Decision:

ECMC
Representative:

2 CA# 203951

Corrective Action: Storm water BMPs and erosion controls (ie: ecofiber, straw mulch, erosion control blankets, etc.) need to be installed and maintained on portions of the project area sparse and bare soils until soils are stabilized with desirable perennial vegetation.

Date: 04/23/2025

Response: CA COMPLETED

Date of Completion: 05/01/2025

Operator Comment: Storm water BMP's and erosion control's have been installed & Maintained where needed. All areas with sparse vegetation and bare soils have been re-seeded and will be monitored for for the growth of desirable vegetation.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Supplemental FIRR after completed work. Remedial Report attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jaime Pugh

Signed: _____

Title: Engineering Analyst

Date: 5/8/2025 7:39:33 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

404195141	Remedial Report
-----------	-----------------

Total Attach: 1 Files