

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/01/2025

Submitted Date:

05/05/2025

Document Number:

713602133

FIELD INSPECTION FORMLoc ID 483009 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10763

Name of Operator: BNL (ENTERPRISE) INC

Address: 6494 S QUEBEC ST

City: ENGLEWOOD State: CO Zip: 80111

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kondrat, Peter	970-759-5370	pkondrat@bluestarhelium.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
483009	LOCATION	AC			-	State 09 SWSE 3054	RI

General Comment:

This is a pre-construction inspection at the JACKSON #02 L4 3154 location.
See all comments and attached photos for inspection observations.

Location Construction

Location ID: 483504 CDP: _____

Comment: The soil type of this area is predominately Chacuaco which consists of topsoil to at least 10 inches that will need to be salvaged. Per Operator topsoil plan, 12" x 12" test pits will be dug in the south and east corners of the wellpad. Photos will be submitted of the test pits via Form 4 prior to construction." It does not appear that the photos of the test pits have been provided.

Corrective Action: Comply with topsoil protection plan and submit photos of the soil test pits.

Date: 05/12/2025

Form 2A COAs:

Comment: A form 42 notice was submitted which had a construction start date of 4/30/2025. No construction had commenced as of 5/1/2025. A 48 hr notice prior to construction will need to be provided.

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: _____

Corrective

Action: _____

Date: _____

On Site Inspection (305):Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404190257	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7035438
713602135	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7035422