

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404210856

Date Received:  
05/20/2025

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

2 of 4 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10417  
Name of Operator: INCREMENTAL OIL & GAS (FLORENCE) LLC  
Address: 113 N SANTA FE AVE  
City: FLORENCE State: CO Zip: 81226

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Hart, Tim</u>		<u>thart@fremontpetroleum.com</u>
<u>Beardslee, Tom</u>		<u>tom.beardslee@state.co.us</u>
<u>Harkins, Liz</u>		<u>lharkins@fremontpetroleum.com</u>
<u>Goss, Aaron</u>	<u>303-495-0327</u>	<u>agoss@fremontpetroleum.com</u>

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 700300214  
Inspection Date: 07/15/2021 FIR Submit Date: 07/23/2021 FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: INCREMENTAL OIL & GAS (FLORENCE) LLC Company Number: 10417  
Address: 113 N SANTA FE AVE  
City: FLORENCE State: CO Zip: 81226

**LOCATION** - Location ID: 417859

Location Name: Woolly Bugger Number: 34-20 County: FREMONT  
Qtrqr: SWSE Sec: 20 Twp: 19S Range: 69W Meridian: 6  
Latitude: 38.376641 Longitude: -105.132744

**FACILITY** - API Number: 05-043-00 Facility ID: 417858

Facility Name: Woolly Bugger Number: 34-20  
Qtrqr: SWSE Sec: 20 Twp: 19S Range: 69W Meridian: 6  
Latitude: 38.376641 Longitude: -105.132744

**CORRECTIVE ACTIONS:**

**1** CA# 154093

Corrective Action: clean up per Rule 1002.f2(c) Date: 07/30/2021

Response: CA COMPLETED Date of Completion: 10/03/2022

Operator dispatched crew on 9/29/22 who cleaned and removed impacted soil and replaced with clean soil. Per FIRR Doc No. 403184315, this CA was completed, and documentation was provided at that time. ECMC

Operator Comment: Inspection No. 695107047, performed on 12/7/2022, confirmed work completed.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

2 CA# 154094

Corrective Action: remove debris/combustible material within 25' of equipment per Rule 606 and 610.k Date: 07/30/2021

Response: CA COMPLETED Date of Completion: 10/03/2022

Operator Comment: Crews had been performing weed maintenance during inspection date of 9/21/22 and weed removal was completed work on 9/22/22. Upon receiving FIR via email on 9/27/22, Operator dispatched pumper to take photos of work completed in area. Per FIRR Doc No. 403184315, this CA was completed, and documentation was provided at that time.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

OPERATOR COMMENT AND SUBMITTAL

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Mackenzie Smith Signed: \_\_\_\_\_

Title: Staff Engineer Date: 5/20/2025 12:42:37 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404210856	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files