

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/12/2025

Submitted Date:

05/16/2025

Document Number:

693808661

**FIELD INSPECTION FORM**Loc ID 316816 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10841

Name of Operator: AMERICAN HELIUM LLC

Address: 23501 CINCO RANCH BLVD, B244

City: KATY State: TX Zip: 77494

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

11 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Joyner, Ryan	970.385.6289	rjoyner@blm.gov	Tres Rios
Lapham, Ken	979-877-4951	klapham@americanhelium.us	All Inspections
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256997	WELL	SI	10/01/2017	GW	113-06074	FOSSIL FEDERAL 8	SI

**General Comment:**

ECMC staff performed a routine field inspection on 5/12/2025.

Issues were found requiring corrective action. See inspection text and photos for details.

Any Corrective Actions from previous inspections that have not been addressed are still applicable.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	
Type	Main		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	06/16/2025
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	435-631-2239		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
In Containment:	No			
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

**Fencing/:**

Type	WELLHEAD		
Comment:	Panel fence		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	Separators disconnected and blind flanged by BLM		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			

Corrective Action:		Date:	
Type: Flow Line	#		
Comment:	Multiple sizes and locations		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Dehydrator	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	<100 BBLs	PBV STEEL		38.074269,-108.695680
Comment:	See Signs/labels CA				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		38.073755,-108.695871
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate



Inspected Facilities									
Facility ID:	256997	Type:	WELL	API Number:	113-06074	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: _____									
Comment: <div>Tubing valve locked out by BLM.</div>									
Corrective Action: _____ Date: _____									
BradenHead									
Date of Last Brhd Test: 05/08/2025      Annual Brhd Completed? Yes									
Last Brhd Test Results      Initial Surf Csg Pressure: 0      Fluid Type: NONE									
End Surf Csg Pressure: 0									
Comment: _____									
Corrective Action: _____ Date: _____									
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404207576	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7052833">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7052833</a>
693808662	Inspection photos 5/12/2025	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7052824">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7052824</a>