

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/02/2025

Submitted Date:

06/02/2025

Document Number:

716301054

FIELD INSPECTION FORMLoc ID 308564 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Costa, Ryan		ryan.costa@state.co.us	
D DYKE, TRACY	719-846-7898	tracy.dyke@enrllc.com	Insp. w/ca's
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274354	WELL	PR	07/14/2005	GW	071-08232	ITTY BITTY 12-31	PR
279705	PIT	AC	09/20/2005		-	ITTY BITTY 12-31 ONSITE	AC

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment:

PHOTO 4: AREA OF IMPACTED OILS AROUND PRIME MOVER ENGINE SKID.

Corrective Action:

Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002.(2).D. THIS IS THE 3RD NOTIVE FOR THIS CORRECTIVE ACTION IMMEDIATE ACTION IS REQUIRED.

Date:

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Vertical Separator

1

Comment:

Corrective Action:

Date:

Type: Progressive Cavity

1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment:

CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

Type: Bradenhead

1

Comment:

IS ACCESSABLE

Corrective Action:

Date:

Type: Deadman # & Marked

4

Comment:

Corrective Action:

Date:

Type: Prime Mover

1

Comment:

Corrective Action:

Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	274354	Type:	WELL	API Number:	071-08232	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR							
Corrective Action:								Date:	
BradenHead									
Date of Last Brhd Test:		11/11/2011		Annual Brhd Completed?					
Last Brhd Test Results		Initial Surf Csg Pressure:		0		Fluid Type:			
		End Surf Csg Pressure:		0					
Comment:		FORM 4 ON FILE							
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	279705	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: PHOTO 5: OILY WASTE IS PRIME MOVER ENGINE SKID (ALTHOUGH IT APPEARS THAT THE SKID HAS BEEN CLEANED SINCE LAST INSPECTION THE EQUIPMENT MAINTANANCE HAS EITHER NOT BEEN PERFORMED OR REPAIRS ARE INADEQUATE).

Corrective Action: DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. (THIS IS THE 3RD INSPECTION OF THIS EQUIPMENT WITH THE SAME COMPLIANCE CONDITIONS LEAKING EQUIPMENT MUST BE REPAIRED OR REPLACED.

Date: 06/03/2025

Pits: ☐ NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 279705 Lat: 37.303340 Long: -104.720816

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective Action

Date: _____

Fencing:

Fencing Type: None Fencing Condition: _____

Comment: _____

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Corrective Action

Date: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: _____

Corrective Action

Date: _____

Permit:	Facility ID	Permit Num	Expiration Date
	279705	1140243	

ECMC Comments

Comment	User	Date
THIS IS A FOLLOW UP TO INSP. DOC #713600939. NOT ALL CA'S HAVE BEEN ADDRESSED, IMMEDIATE ACTION IS REQUIRED.	beardslt	06/02/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716301055	INSP. PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7079033