

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/20/2025

Submitted Date:

05/29/2025

Document Number:

697602505**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Ahmadian, Alexander 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 555 17TH STREET SUITE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	
Evans, Jacob		jevans@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
489316	SPILL OR RELEASE	CL	02/13/2025		-	Kane 20-10	EI

General Comment:

ECMC Environmental Inspection to determine progress on the Kane 20-10 (Spill ID 489316). Any corrective actions from previous inspections, forms, or orders that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Location				
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date: _____
Corrective Action:				
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	Unnecessary remnants of old fencing and fence posts left on location. Weeds beginning to grow on location.			
Corrective Action:	Comply with housekeeping Rule 606.			Date: 06/05/2025
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	489316	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental	
Spill/Remediation:	
Comment:	Form 19 Document #404093096 was submitted and approved. Move to Remediation Project #37667.
Corrective Action:	<div></div> <div>Date: <div></div></div>
Emission Control Burner (ECB): <div></div>	
Comment:	<div></div>
Pilot: <div></div>	Wildlife Protection Devices (fired vessels): <div></div>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Stormwater BMPs have been installed around the location to prevent run-off

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404222577	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7073309
697602506	Photolog	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7073306