

TEP
KP 22-22
Location ID: 420972



Location



Location

TEP
KP 22-22
Location ID: 420972



Location




Location

TEP
KP 22-22
Location ID: 420972



Some well signs are illegible



Some well signs are illegible

TEP
KP 22-22
Location ID: 420972




Load line lacking cap



Load line lacking cap

TEP
KP 22-22
Location ID: 420972



Hole in containment



Hole in containment

TEP
KP 22-22
Location ID: 420972



Debris



Lack of stabilization/compaction

TEP
KP 22-22
Location ID: 420972



Lack of stabilization/compaction



Access road has areas of stabilization issues and lack of tracking controls

TEP
KP 22-22
Location ID: 420972



Access road has areas of stabilization issues