

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404241153

Date Received:

06/15/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714002150

Inspection Date: 05/08/2025

FIR Submit Date: 05/12/2025

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 385638

Location Name: LOBATO-N35N8W Number: 27NESE County: _____

Qtrqtr: NESE Sec: 27 Twp: 35N Range: 8W Meridian: N

Latitude: 37.273616 Longitude: -107.726745

FACILITY - API Number: 05-067- -00 Facility ID: 385638

Facility Name: LOBATO-N35N8W Number: 27NESE

Qtrqtr: NESE Sec: 27 Twp: 35N Range: 8W Meridian: N

Latitude: 37.273616 Longitude: -107.726745

CORRECTIVE ACTIONS:

1 CA# 204709

Corrective Action: Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

Date: _____

Response: CA COMPLETED

Date of Completion: 06/12/2025

Operator Comment: Reseeding was done with hydromulch this time (versus 2024 reseeded) to see if that increases the likelihood of vegetative success. Also, we are in conversation with the landowner about fencing if the horses come back to this area.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective action completed. See attachment for photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lisa Paulek

Signed: _____

Title: permitting specialist II

Date: 6/15/2025 8:54:54 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

404241153	FIR RESOLUTION SUBMITTED
404241155	Lobato 1-27 CA photos

Total Attach: 2 Files