

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/03/2025

Submitted Date:

06/12/2025

Document Number:

710500549

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Sanchez, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 17180

Name of Operator: CITATION OIL & GAS CORP

Address: 14077 CUTTEN RD

City: HOUSTON State: TX Zip: 77069

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kennedy, Herschel	719-767-8851	hkennedy@cogc.com	COGC
Costa, Ryan		ryan.costa@state.co.us	
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	COGC

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412072	GAS COMPRESSOR STATION	AC			-	EAST SORRENTO COMPRESSOR	EI
488537	SPILL OR RELEASE	AC	04/30/2025		-	East Sorrento Compressor	EI

General Comment:

This is an Environmental Inspection for the East Sorrento Compressor, Facility ID 412072 located in Cheyenne County, CO. Spill ID 488537

Inspected Facilities

Facility ID: 412072 Type: GAS API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 488537 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spill/Remediation:

Comment: This is an Environmental Inspection for Spill ID 488537. At the time of inspection, there was no open excavation or evidence of an active spill investigation. Spill Discovery date 11/18/2024, at the time of inspection the spill facility is 107-days past the 90-day closure window in accordance with Rule 912.b.(6).

Form 19-s document # 404062569 received on 4/11/2025 requested Closure for Spill ID 488537. ECMC removed the final closure request for the following reasons: ECMC removed the final closure request for this Form 19, The pH of soil samples collected at the site exceeds the allowable level for Table 915-1 soil suitability for reclamation and exceeds the background sample presented. Therefore, Operator will define the extent of soil with elevated pH, and if Operator proposes to leave soil with elevated pH in place, Operator will submit a Reclamation plan pursuant to Rule 915.b.

Background samples collected @ E_SORRR_BG@6' and E_SORR_BG@9 show signs of elevated SAR and EC. Operator shall collect additional background samples from an area up gradient outside of the disturbance areas from the location to confirm elevated levels of SAR and EC are natural occurring.

Operator shall file a Form 27-i for ongoing spill remediation/investigation

Corrective Action: Operator shall comply with Rule 912.b.(6). Date: 06/26/2025

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

ECMC Comments

Comment	User	Date
All previously assigned COAs and CAs shall apply	sanchezcc	06/12/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404239028	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7093356
710500550	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7093349