

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/19/2025

Submitted Date:

06/19/2025

Document Number:

719000267

FIELD INSPECTION FORM

Loc ID: 326281 Inspector Name: GARCIA, CHARLES On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10663
Name of Operator: ENDURING RESOURCES LLC
Address: 6300 S SYRACUSE WAY, SUITE 525
City: CENTENNIAL State: CO Zip: 80111

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Huntington, Heather		hhuntington@enduringresources.com	SJB inspections
Walter, Klye		kwalter@enduringresources.com	SJB inspections

General Comment:

Inspection Report Summary
On 6/19/25 I Inspector Charles Garcia conducted an FOLLOW UP ON CA'S FROM DOC #719000019
Location: Burnett 2-1
Operator: Enduring resources
API#: 067-07769
County: LaPlata
Separator and partially buried vessel have been removed since last compliance inspection. No Form 42 notice of major change or Form 27s in well file. See Equipment and Tank sections for corrective actions
FIR 2 OF 4 CA'S RESOLVED FIR DOC#404214169
CA# 204184 FORM 27 FILED 5/20/25 FORM 404192142
CA# 204186 FORM 27 FILED 5/20/25 FORM 404192142

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000268	FIR RESOLUTION	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7103514