




RAT Observation

- No Observed Source Material (15)
- Possible Source Material (0)
- Source Material Observed (0)



Observation

Oiling Observation: **0 No Observable Oil** | Id: 536782 | 4/28/2025 8:44:54 AM
(40.493399, -104.608946)
No obvious presence of hydrocarbons on play set





T156-1 RES - SELBY DOUGLAS LEE - 23605 CR 70 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: 0 No Observable Oil | Id: 536778 | 4/28/2025 9:16:59 AM
(40.493976, -104.609249)
No obvious presence of hydrocarbon on small silo





T156-1 RES - SELBY DOUGLAS LEE - 23605 CR 70 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: 0 No Observable Oil | Id: 536849 | 4/28/2025 9:17:19 AM
(40.494634, -104.608756)

No evidence of hydrocarbon contamination on vegetation or surrounding structures





T156-1 RES - SELBY DOUGLAS LEE - 23605 CR 70 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: 0 No Observable Oil | Id: 536877 | 4/28/2025 9:18:19 AM
(40.494418, -104.608699)
No indication of contamination, grassy field within fencing



Oiling Observation: 0 No Observable Oil | Id: 536779 | 4/28/2025 9:19:36 AM
(40.49406, -104.609023)
No obvious presence of hydrocarbon at chicken coop





T156-1 RES - SELBY DOUGLAS LEE - 23605 CR 70 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: 0 No Observable Oil | Id: 536863 | 4/28/2025 9:21:04 AM
(40.493725, -104.608697)

No evidence of contamination found.





T156-1 RES - SELBY DOUGLAS LEE - 23605 CR 70 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: 0 No Observable Oil | Id: 536777 | 4/28/2025 9:23:27 AM
(40.494004, -104.608892)
No obvious presence of hydrocarbons at car shed





T156-1 RES - SELBY DOUGLAS LEE - 23605 CR 70 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: 0 No Observable Oil | Id: 537705 | 4/28/2025 9:25:29 AM
(40.493387, -104.608698)
No indication of contamination.





T156-1 RES - SELBY DOUGLAS LEE - 23605 CR 70 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: 0 No Observable Oil | Id: 536774 | 4/28/2025 9:29:26 AM
(40.493789, -104.609315)
No obvious presence of hydrocarbons on doghouse or garden shed



Oiling Observation: 0 No Observable Oil | Id: 536773 | 4/28/2025 9:30:38 AM
(40.493961, -104.609371)
No obvious presence of hydrocarbons on truck camper

