



RAT Observation

- No Observed Source Material (4)
- Possible Source Material (0)
- Source Material Observed (0)

Observation

Oiling Observation: **0 No Observable Oil** | Id: 546032 | 5/9/2025 1:15:00 AM
(40.523253, -104.574801)

Dumpster on South side in front residence. No hydrocarbons detected





T017 RES - SANFORD SCOTT WILLIAM - 25409 CR 74 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: 0 No Observable Oil | Id: 546040 | 5/9/2025 1:02:32 PM
(40.523405, -104.574579)
West side of property. Jet skis





T017 RES - SANFORD SCOTT WILLIAM - 25409 CR 74 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: 0 No Observable Oil | Id: 546041 | 5/9/2025 1:09:17 PM
(40.523398, -104.574698)
South West side of main residence. No hydrocarbons detected.





T017 RES - SANFORD SCOTT WILLIAM - 25409 CR 74 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: 0 No Observable Oil | Id: 546047 | 5/9/2025 1:24:05 PM
(40.522812, -104.574212)

Mailbox on South side against road. No hydrocarbons detected.

