




RAT Observation

- No Observed Source Material (4)
- Possible Source Material (0)
- Source Material Observed (0)





T144 RES - ROBERT R STONE AND ARLENE M STONE TRUST -
35909 CR 49 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Observation

Oiling Observation: 0 No Observable Oil | Id: 553363 | 5/21/2025 8:39:54 AM
(40.520574, -104.602312)
South side of Red Barn facing well





T144 RES - ROBERT R STONE AND ARLENE M STONE TRUST -
35909 CR 49 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: 0 No Observable Oil | Id: 553365 | 5/21/2025 9:20:17 AM
(40.520824, -104.602078)
Secondary building connected to red shop.





T144 RES - ROBERT R STONE AND ARLENE M STONE TRUST -
35909 CR 49 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: 0 No Observable Oil | Id: 553366 | 5/21/2025 9:24:47 AM
(40.520651, -104.602147)
Main residence South side facing well





T144 RES - ROBERT R STONE AND ARLENE M STONE TRUST -
35909 CR 49 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: 0 No Observable Oil | Id: 553367 | 5/21/2025 9:29:31 AM
(40.520766, -104.602463)
Small shed on North end of property

