

# Harker Ranch Morrow Unit (HRMU 7)

## Well & Location

### Photo Log

**Inspection Comment:** There are oil containers inside the shed which are not stored in containment and there is stained oily soils inside the shed.

**Corrective Action Requested:** Implement or modify BMPs for improved material handling and spill prevention. Immediately clean up area. 24-48 hours to implement improved procedures.

**Description of Compliance:** Oil containers inside the shed have been stored in containment. Stained soil has been cleaned up.

