

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404146474

Date Received:
06/30/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:
2 of 3 CAs from the FIR responded to on this Form
2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
TEP		COGCCInspectionReports@terraep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708303508
Inspection Date: 02/26/2025 FIR Submit Date: 02/26/2025 FIR Status:

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335313

Location Name: CHEVRON-66S96W Number: 20SWSE County:
Qtrqtr: SWSE Sec: 20 Twp: 6S Range: 96W Meridian: 6
Latitude: 39.504328 Longitude: -108.130307

FACILITY - API Number: 05-045-00 Facility ID: 335313

Facility Name: CHEVRON-66S96W Number: 20SWSE
Qtrqtr: SWSE Sec: 20 Twp: 6S Range: 96W Meridian: 6
Latitude: 39.504328 Longitude: -108.130307

CORRECTIVE ACTIONS:

1 CA# 202711

Corrective Action: Replace sign to comply with Rule 605.d. Date: 03/29/2025

Response: CA COMPLETED Date of Completion: 04/01/2025

Operator Comment: New sign is installed. Corrective Action complete.

ECMC Decision:

ECMC
Representative:

3 CA# 202713

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 03/14/2025

Response: CA COMPLETED

Date of Completion: 03/03/2025

Operator
Comment:

Location and access road have been bladed/graded to remove rill erosion. Corrective Action complete.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA #202711: New sign is installed. Corrective Action complete.
CA #202712: Wellhead cellars have been covered. Corrective Action complete.
CA #202713: Location and access road have been bladed/graded to remove rill erosion. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: _____

Title: TEP Representative

Date: 6/30/2025 12:24:56 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files