




**RAT Observation**

- No Observed Source Material (4)
- Possible Source Material (0)
- Source Material Observed (0)



**Observation**

Oiling Observation: **0 No Observable Oil** | Id: 560100 | 5/30/2025 2:05:16 PM  
(40.493999, -104.60993)

No obvious signs of hydrocarbon on either horse trailer or lowboy trailer Northwest of residence



Oiling Observation: 0 No Observable Oil | Id: 560092 | 5/30/2025 2:07:15 PM  
(40.493999, -104.60993)

No obvious signs of hydrocarbons and small tan horse, trailer or present on collapsed camper trailer in front of horse trailer west of residence





T165-1 RES - PETERSON SUSAN K - 23603 CR 70 WELD  
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC  
Incident Date April 7, 2025  
City Galeton, CO  
County Weld

Oiling Observation: 0 No Observable Oil | Id: 560082 | 5/30/2025 2:12:21 PM  
(40.493683, -104.609469)  
No obvious signs of hydrocarbon on hanger style barn north of residence





T165-1 RES - PETERSON SUSAN K - 23603 CR 70 WELD  
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC  
Incident Date April 7, 2025  
City Galeton, CO  
County Weld

Oiling Observation: 0 No Observable Oil | Id: 560097 | 5/30/2025 2:13:29 PM  
(40.493765, -104.609714)

No obvious signs of hydrocarbon spray on either north or west side where affected area would be

