



RAT Observation

- No Observed Source Material (16)
- Possible Source Material (0)
- Source Material Observed (0)



T167-1 RES - GODDARD DONALD - 23757 CR 70 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Observation

Oiling Observation: 0 No Observable Oil | Id: 534353 | 4/25/2025 9:10:32 AM
(40.496217, -104.606108)
No obvious presence of hydrocarbons on side of the house





T167-1 RES - GODDARD DONALD - 23757 CR 70 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: 0 No Observable Oil | Id: 534352 | 4/25/2025 9:12:01 AM
(40.496435, -104.606166)

No obvious hydrocarbons on metal structures cars have been washed since incident



Oiling Observation: 0 No Observable Oil | Id: 534351 | 4/25/2025 9:13:54 AM
(40.496458, -104.606185)
No obvious hydrocarbons on wooden fence at horse corral





T167-1 RES - GODDARD DONALD - 23757 CR 70 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: 0 No Observable Oil | Id: 534367 | 4/25/2025 9:17:15 AM
(40.496419, -104.60614)
No impact of hydrocarbons on Jeep or equipment



Oiling Observation: 0 No Observable Oil | Id: 534355 | 4/25/2025 9:18:20 AM
(40.496421, -104.606142)
No hydrocarbon impact on buildings west of main living quarters





T167-1 RES - GODDARD DONALD - 23757 CR 70 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: 0 No Observable Oil | Id: 534358 | 4/25/2025 9:21:15 AM
(40.496629, -104.606185)
No obvious impact of hydrocarbons at horse corral west of main living quarters





T167-1 RES - GODDARD DONALD - 23757 CR 70 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: 0 No Observable Oil | Id: 534354 | 4/25/2025 9:22:31 AM
(40.496235, -104.605426)
No obvious impact of hydrocarbons on horse trailers or regular trailers



Oiling Observation: 0 No Observable Oil | Id: 534360 | 4/25/2025 9:26:32 AM
(40.496426, -104.605814)
No obvious impact of hydrocarbons on fencing





T167-1 RES - GODDARD DONALD - 23757 CR 70 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: 0 No Observable Oil | Id: 534362 | 4/25/2025 9:33:08 AM
(40.495956, -104.606353)
No obvious impact of hydrocarbons on horse trailer





T167-1 RES - GODDARD DONALD - 23757 CR 70 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: 0 No Observable Oil | Id: 534531 | 4/25/2025 10:42:27 AM
(40.495864, -104.605816)

No observed contamination on topsoil or vegetation

