




RAT Observation


- No Observed Source Material (10)
- Possible Source Material (0)
- Source Material Observed (0)



Observation

Oiling Observation: **0 No Observable Oil** | Id: 555321 | 5/23/2025 9:16:13 AM
(40.493094, -104.594401)

No presence of contamination found. Slight yellowing to crops near base.





T119 AG - PETTINGER MATTHEW J - 37485 COUNTY ROAD 57
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: 0 No Observable Oil | Id: 555344 | 5/23/2025 9:19:31 AM
(40.492873, -104.594575)

No presence of contamination found. Slight yellowing to crops near base.





T119 AG - PETTINGER MATTHEW J - 37485 COUNTY ROAD 57
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: 0 No Observable Oil | Id: 555359 | 5/23/2025 9:21:11 AM
(40.492578, -104.594756)

No presence of contamination found. Slight yellowing to crops near base.





T119 AG - PETTINGER MATTHEW J - 37485 COUNTY ROAD 57
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: 0 No Observable Oil | Id: 555362 | 5/23/2025 9:24:30 AM
(40.492178, -104.595013)
No presence of contamination found





T119 AG - PETTINGER MATTHEW J - 37485 COUNTY ROAD 57
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: 0 No Observable Oil | Id: 555337 | 5/23/2025 9:26:02 AM
(40.491798, -104.595306)
No presence of contamination found





T119 AG - PETTINGER MATTHEW J - 37485 COUNTY ROAD 57
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: 0 No Observable Oil | Id: 555324 | 5/23/2025 9:27:34 AM
(40.491442, -104.595473)
No presence of contamination found





T119 AG - PETTINGER MATTHEW J - 37485 COUNTY ROAD 57
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: 0 No Observable Oil | Id: 555331 | 5/23/2025 9:28:53 AM
(40.491069, -104.59573)
No presence of contamination found





T119 AG - PETTINGER MATTHEW J - 37485 COUNTY ROAD 57
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: 0 No Observable Oil | Id: 555358 | 5/23/2025 9:30:25 AM
(40.490676, -104.595973)
No presence of contamination found





T119 AG - PETTINGER MATTHEW J - 37485 COUNTY ROAD 57
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: 0 No Observable Oil | Id: 555351 | 5/23/2025 9:31:44 AM
(40.490321, -104.596186)
No presence of contamination found





T119 AG - PETTINGER MATTHEW J - 37485 COUNTY ROAD 57
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: 0 No Observable Oil | Id: 555366 | 5/23/2025 9:32:49 AM
(40.490048, -104.596369)
No presence of contamination found

